

Biking Along North Main Street

The bicycle network is fragmented, forcing riders into high-stress traffic conditions.





Image shows a biker crossing North Main Street without a safe crosswalk.



Image shows a bicyclist riding on the eastside sidewalk north of Depot Street.



Image shows car traffic and biker crossing North Main Street.



TOOLE DESIGN

Geographic and mapping information presented in this document is for informational purposes only, and is not suitable for legal, engineering, or surveying purposes. Mapping products presented herein are based on information collected at the time of preparation. Toole Design Group, LLC makes no warranties, expressed or implied, concerning the accuracy, completeness, or suitability of the underlying source data used in this analysis, or recommendations and conclusions derived therefrom.