

Walking Along North Main Street

North of Summit Street, sidewalks, crossings, and lighting become inconsistent.





Image shows person running on sidewalk north of Depot Street.



Image shows limited lighting at Summit Street intersection.



Image shows pedestrians crossing North Main Street.



TOOLE
DESIGN

Geographic and mapping information presented in this document is for informational purposes only, and is not suitable for legal, engineering, or surveying purposes. Mapping products presented herein are based on information collected at the time of preparation. Toole Design Group, LLC makes no warranties, expressed or implied, concerning the accuracy, completeness, or suitability of the underlying source data used in this analysis, or recommendations and conclusions derived therefrom.